


**NYS Department of Environmental Conservation  
Division of Environmental Remediation  
Bureau of Hazardous Site Control  
50 Wolf Road, Albany, New York 12233-7010**



**John P. Cahill  
Commissioner**

March 31, 1998

Mr. Peter Koutroubis  
BRAC Environmental Coordinator  
Department of the Army  
New York Area Command and Fort Hamilton  
Directorate of Public Works, Bldg. 129  
Environmental Division  
Brooklyn, NY 11252-6800

**Re: Groundwater Data - 4<sup>th</sup> Round  
Fort Totten (BRAC Area)  
NYSDEC Site ID #241017A**

Dear Peter:

I have received and reviewed the above-mentioned groundwater data from samples collected on January 8 and 9, 1998 by your consultant (ICF Kaiser Engineers, Inc.).

Based on this data, it is my opinion that no further groundwater monitoring is needed at the site. All of the contaminants of concern are at or below 6NYCRR Part 703.5 standards.

If you have any questions or comments on this letter, please contact me at (518) 457 - 0639.

Sincerely,

David K. Harrington  
Environmental Engineer 1  
Eastern Investigation Section  
Bureau of Hazardous Site Control

cc: D. Mather, EPA - Region 2

